

ROAD / STREET	START	END	PAVEMENT RATING	RECOMMENDED PROCESS	Total Cost	Comments
Calico Court	All		83	Crack Seal and Micro Surfacing	2556.83	Decent Shape / Good Profile
Old Springfield Road	Chillicothe	north corp limit	80	Crack Seal and Micro Surfacing	6593.33	No Big issues at This Time
William Street - North	Liberty	John	80	Micro Surfacing	2129.16	Old Chip Seal / SWEEP
John Street	All		80	Micro Surfacing	1917.5	Old Chip Seal / SWEEP
Section Line Drive	All		75	Crack Seal with Cape Seal	12675.55	Raveling
Section Line Drive (offset)	All		75	Crack Seal with Cape Seal	2583.33	Raveling
Overlook Drive	All		75	Crack Seal with Cape Seal	5545.55	Raveling
Dry Creek Way	All		75	Crack Seal with Cape Seal	3881.88	Raveling
Fence Row Lane	All		75	Crack Seal with Cape Seal	8920.42	Raveling
Hayloft Drive	All		75	Crack Seal with Cape Seal	2725.24	Deep Cracks and Raveling
Berschet Drive	All		72	Crack Seal with Cape Seal	31365.11	Much Surface Cracking / 5 sy of Partial Depth Repair
Rankin Avenue	south term limit	Jamestown	70	Crack Seal with Cape Seal	9076.11	Crack Seal Worse Cracks / SWEEP
Mound Street	address 14	Church	63	Asphalt Mill and Fill with Rejuvenator	17388	Deep Cracks with Vegetation Growth
James Court	All		63	Asphalt Mill and Fill with Rejuvenator	39136.5	Deep Cracks / Many Areas Coming Apart
Waldeck Drive	All		63	Asphalt Mill and Fill with Rejuvenator	14094	Raveling / Deep Cracks
Willow Street	All		63	Asphalt Mill and Fill with Rejuvenator	42768	Shoulders Bad / Parabolic / SWEEP
Sunset Court	All		63	Asphalt Mill and Fill with Rejuvenator	3881.25	Deep Trasnverse Cracks / Asphalt High at Gutter
Overlook Court	All		62	Asphalt Mill and Fill with Rejuvenator	15990.75	Bad Transverse Cracking with Raveling
Liberty Street	All		62	Asphalt Mill and Fill with Rejuvenator	14391	Old Chip Seal / Bad Ride
Jamestown Street	Jamestown Road	Rankin	60	Asphalt Mill and Fill with Rejuvenator	95208.75	Composite Pavement - Needs Chip Interlayer
Mound Street	William	address 14	60	Asphalt Mill and Fill with Rejuvenator	20779.2	Deep Cracks with Vegetation Growth
Clifton Road	All		60	Asphalt Mill and Fill with Rejuvenator	62193.15	Much patching / Bad Ride with Deep Cracks
Jamestown Road	Mound	Columbus	60	Asphalt Mill and Fill with Rejuvenator	76950	
Church Street	Columbus	Jamestown	58	Asphalt Mill and Fill with Rejuvenator	22125.15	Many Patches /SWEEP
Church Street	Jamestown	Mound	58	Asphalt Mill and Fill with Rejuvenator	36418.95	Much Cracking / Many Patches
Mound Street	Jamestown	William	58	Asphalt Mill and Fill with Rejuvenator	69741	High Crown in Areas / Asphalt High to Curb
William Street - South	Mound	High	58	Asphalt Mill and Fill with Rejuvenator	7695	Bad Shoulders Due to Industry
Liberty Circle	All		57	Asphalt Mill and Fill with Rejuvenator	11407.5	Old Chip Seal / Bad Ride
Murray Drive	All		57	Asphalt Mill and Fill with Rejuvenator	28572.75	Shoulders Bad / Bad Drainage
Sunset Lane	All		56	Asphalt Mill and Fill with Rejuvenator	10530	Coming Apart / Bad Ride
Walnutn Street	All		55	Asphalt Mill and Fill with Rejuvenator	13365	Bad Ride / Potholes / Much Cracking
Oak Street Street	All		55	Asphalt Mill and Fill with Rejuvenator	11026.12	Bad Ride / Potholes / Much Cracking
Church Street	Mound	Woodward	55	Asphalt Mill and Fill with Rejuvenator	25806.6	Much Cracking / Worse Towards Woodward
Jamestown Street	Rankin	Walnut	55	Asphalt Mill and Fill with Rejuvenator	16200	Bad Ride

Rankin Avenue	Jamestown	Columbus	54	Asphalt Mill and Fill with Rejuvenator	17749.8	Bad Shouldess / Moisture Retension Issues
Collins Avenue	All		54	Asphalt Mill and Fill with Rejuvenator	15774.75	Bad Shoulders / Bad Ride
High Street	All		53	Asphalt Mill and Fill with Rejuvenator	27060.75	Mostly Gravel Covered / Clean and Sweep
Jamestown Road	south corp limit	address 324	53	Asphalt Mill and Fill with Rejuvenator	7456.05	
Jamestown Road	address 324	Mound	52	Asphalt Mill and Fill with Rejuvenator	11178	
Sprague Road	All		50	Asphalt Mill and Fill with Rejuvenator	42560.1	Much Failure / Shoulders Are Real Bad
Short Street	All		50	Asphalt Mill and Fill with Rejuvenator	8259.3	Bad Shape / Coming Apart by Jamestown
William Street - South	SRS 42	Jamestown	40	Asphalt Mill and Fill with Rejuvenator	19095.75	Worst Street in the Village
William Street - South	Jamestown	Mound	40	Asphalt Mill and Fill with Rejuvenator	24367.5	Worst Street in the Village
TOTALS					919,140.73	